


Oxine peak



Oxine is a metal chelating compound. It is considered that Company P and Company S shows a low theoretical plate number and tailing. This means that they have a lot of metal impurities

Company W has a bad peak shape.

SunShell C18 shows a good peak shape which shows that SunShell C18 has little metal impurities.